



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
THE QUADRANT	O/S 42	Dangerous	Stems splitting apart	Laburnum anagyroides	Plant in verge o/s 45, (same position as felled tree)	Malus 'Rudolph'
THE QUADRANT	O/S 23A	Damaging	F/W damaged by shallow rooting	Prunus Kanzan	Plant in verge between 23A and 23B in line with boundary, (same position as felled tree)	Malus 'Rudolph'
THE QUADRANT	O/S 21b	Damaging	Kerb displaced by rooting immediately behind	Prunus Kanzan	Plant in verge between 23 and 21B in line with boundary, (same position as felled tree)	Malus 'Rudolph'